



## WEEKLY SUMMARY REPORT

<b>PROJECT NO.:</b>	2476.0001Y002	<b>WEEKLY REPORTING PERIOD:</b> Monday June 6, 2016 through Sunday June 12, 2016
<b>PROJECT:</b>	CFAC Phase I Site Characterization	
<b>LOCATION:</b>	Near Columbia Falls, Montana	

### SUMMARY OF WORK COMPLETED

- Surface water sampling
  - Roux Associates collected 10 surface water samples from locations where surface water is currently present due to high spring flow. Samples collected from:
    - Three locations in the South Percolation Ponds
    - Five locations in the Cedar Creek Reservoir Overflow Drainage Ditch
    - Two locations in the area northwest of the West Landfill and South of the Industrial Landfill
  - Samples sent to TestAmerica, Edison, NJ and TestAmerica, Sacramento, CA for laboratory analysis
- Deployed pressure transducer at newly installed monitoring well CFMW-003

### SUMMARY OF WORK PLANNED FOR NEXT WEEK / ANTICIPATED SCHEDULE CHANGES

- Planned
  - Resume drilling program with the advancement of soil borings and installation of monitoring wells
  - Begin incremental soil sampling within operational grid area
  - Collect waste characterization soil sample from container #1
- Modifications
  - No modifications to schedule

### HEALTH AND SAFETY NOTES

- Roux Associates personnel reviewed surface water sampling procedures and discussed health and safety while working around surface water bodies

### OTHER NOTES

- No additional notes

Prepared By Michael Ritorto Of Roux Associates, Inc.